Work Order ID 69295 Friday, May 06, 2011 1:01:08 PM D3272-1 Item ID: Revision ID: Item Name: Step 5/6/2011 **Start Qty: 10.00 Start Date:** Required Date: 5/27/2011. Req'd Qty: 10.00 Reference: Process Plan: M Approvals: QC: Sequence ID/ Operation Work Center ID Description

Accept



Setup Start



Cust Item 1D:

Date:

Customer:

Tool ID

Date: \\-OS-O9 Tooling:

Date: _____

SPC (Y/N):

Set Up/

Run Hours

Date:

NE11.05.17 10 \$

Run Start



Stop

Reject Reject Tool # Plan Accept Insp. Qty Qty Code Number Stamp

Draw Nbr Revision Nbr D3272 Rev B

100

Large Fab

Large Fab

Large Fab

0.00

0.00

SOUARE ONE END BEFORE CUTTING OTHER END

1-Cut D2622-120 extrusion to 116.25" long as per Dwg D3272 using cutting table setup DT 8185-2A

2-Drill extrusion as per Dwg D3272 using Jig DT8680 for rivets.

3-Deburr

QC6- Inspect dimensions to drawing

0.00

Quality Control

110

Memo

0.00

Dart Aerospace Ltd

W/O:			W	ORK ORDER CHAN	GES					
DATE	STEP	PRO	OCEDURE CHA	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										ļ
_		<u>. </u>			-					
	-									
Part No	:	PAR #:	Fault Cate	egory:	NCF	l: Yes I	No DQ	4:	Date:	
		esolution:								
NCR:	٠.		WORK ORD	ER NON-CONFORM	MANCE	(NCR)			
DATE	STEP	Description of NC			ection B	Ciam 9		ation	Approval	Approval
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	1	Sign & Date	Secti	on C	Chief Eng	QC Inspector
			•					•		
NOTE: D	ate & initi	al all entries							•	

Work Order ID 69295

Friday, May 06, 2011 1:01:08 PM



Page 2

Item ID:

D3272-1

Accept

Setup Start

Stop

Revision ID:

Item Name: Start Date:

Step

5/6/2011

QC:

Start Qty: 10.00 Req'd Oty: 10.00

Cust Item 1D:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Start Run

Stop



Required Date: 5/27/2011

Date: _____

SPC (Y/N):

Set Up/

Run Hours

Tool ID

Tool # Plan

Reject Accept Qty Qty

Reject Number Stamp

Insp.

Sequence ID/ Work Center ID

120

Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location: WA

0.00

0.00

Code

Date:

Pr11.05.18 10

130 -

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

Memo

0.00

M11-03-18

Dart Aerospace Ltd

	•									
W/O:			WC	RK ORDER CHAN	GES					
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		533333333								
		<u>.</u> .								
Part No	:	PAR #:	Fault Cate	gory:	NCR:	Yes	No DQ	A:	_ Date: _	
	R	esolution:	Disposition	n:	QA: I	WC Cld	sed:		Date: _	
NCR:		1	WORK ORDI	ER NON-CONFORM	MANCE	(NCR)			
D.4.T.E.	0750	Description of NC			ection B		Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	1	Sign & Date		ion C	Chief Eng	QC Inspector
	,									
									,	

NOTE: Date & initial all entries

Picklist Print

Friday, May 06, 2011 1:01:06 PM

Work Order ID: 69295

D3272-1 Parent Item: Parent Item Name: Step



Start Date: 5/6/2011

Required Date: 5/27/2011

Start Qty: 10.00

Required Qty: 10.00

Comments:

IPP Rev:A New Issue 07-06-09 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2622-120C		Manufactured	No			100	Each	100.0000	1	10	Y 11-06	5 - 18	-

Step Extrusion

Location	Loc Qty	Loc Code	
HALL	9		
64409	9		***************************************
WA	91		
46910	2		•
_66970	89		10

Page 1

Dart Aerospace Ltd

W/O:			WC	RK ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CHA	NGE	В	′	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									44444	
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: Y	es N	lo DQ	A:	_ Date: _	
	R	esolution:	Dispositio	n:	_ QA: N/	C Clo	sed:		Date: _	
NCR:		1	WORK ORD	ER NON-CONFORMA	ANCE (N	ICR)				
DATE	STEP	Description of NC		Corrective Action Section			Verific	cation	Approval	Approval
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Sect	ion C	Chief Eng	QC Inspector

NOTE: Date & initial all entries



	DESIG	"p	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CANAD	
ı	CHECK	(ED	APPROVED,	DRAWING NO.	REV. B
	(E	世	D3272	SHEET 1 OF 3
	DATE			TITLE	SCALE
	07.0	5.18		STEP ASSEMBLY, HI LONG	NTS
	Α		04.03.01	NEW ISSUE	
	В		07.05.18	D3272-1 WAS D2622-120	

0706 04


#69245

QTY	QTY		
-041	-042	PART NUMBER	DESCRIPTION
Х		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	Х	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STÉP
16	16	MS20600AD4W4	RIVET.
			į.

GENERAL NOTES:


- D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1 POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3 BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.

			1
-	·		





DESIGN	DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CAN	
CHECKED	APPROVED	DRAWING NO. D3272	REV. B SHEET 3 OF 3
DATE		TITLE	SCALE
07.05.18		STEP ASSEMBLY, HI LONG	1:20



Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

•

1, 1,51.

•

.

,

.

\$<2